## **BUILDING SAFETY CERTIFICATE**

No. 11

Dated: 12/01/2024

Certified that the existing building PEARL ROSARY SCHOOL (NEW) at DAKSHIN

RAJYADHARPUR, P.O MALLICKPARA, P.S SERAMPORE, HOOGHLY — 712203 comprised of 01

Block G + 2 Floors ( Class Room -28 , All Laboratory , Library and Ramp to access upper floors ), 02 Block ( Class Room - 12 , Administrative office , Auditorium - 1 , Activity

Room - 1, Digital Room — 2 , Lift to access upper floors ) , 03 Block ( Staff residential

Room ) owned/occupied by PEARL ROSARY SCHOOL (NEW)have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Assistant Engineer , Hooghly Zilla Patishad , Govt of West

Bengalon10/01/2024 in the presence of Mr. Bikram Paul correspondence , PEARL ROSARY SCHOOL (NEW) and that the building/premises is fit for occupancy upto classes XII with effect from10/01/2024 for a period of 20 years in accordance with rule and subject to compliance of the specific conditions as appended.

compliance of the specific condition	ns as appended.
(1) (2) Issued on 12/01/2024	Arup Bis was  Assistant Engineer 121 01 /202  Hooghly Zilla Parishad
	Signature with Seal :

Designation

Address